

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY
REGION VI
1600 PATTERSON, SUITE 1100
DALLAS, TEXAS 75201

APRIL 9, 1976

MCGINNES INDUSTRIAL MAIN CORP
MS BETTY WEINERT GROMATZKY
5619 GRIGGS ROAD
HOUSTON TC 77021

SUBJECT: NPDES PERMIT NO. TX0004910

GENTLEMEN:

THE ABOVE REFERENCED NATIONAL POLLUTANT DISCHARGE ELIMINATION SYSTEM (NPDES) PERMIT RECENTLY ISSUED TO AUTHORIZE THE DISCHARGE FROM YOUR FACILITY REQUIRES SUBMISSION OF PERIODIC REPORTS TO ALLOW US TO MONITOR YOUR COMPLIANCE WITH THE PERMIT. PLEASE READ YOUR PERMIT CAREFULLY.

YOUR PERMIT MAY REQUIRE THE SUBMISSION OF SCHEDULE OF COMPLIANCE REPORTS (SEE THE COMPLIANCE SCHEDULE SECTION OF YOUR PERMIT). IF YOU DO HAVE A SCHEDULE OF COMPLIANCE, PLEASE TAKE NOTE OF THE DATES YOUR REPORTS ARE DUE TO AVOID BEING IN VIOLATION OF YOUR PERMIT.

IN ADDITION TO ANY REPORT DUE AS THE RESULT OF A COMPLIANCE SCHEDULE, A SEPARATE DISCHARGE MONITORING REPORT (DMR) EPA FORM 3320-1 (10-72) SHOULD BE PREPARED FOR EACH MONTH OF THE REQUIRED REPORT PERIOD. DMR FORMS SHOULD BE SUBMITTED ON A NORMAL SCHEDULE OF FOUR TIMES A YEAR, UNLESS SPECIFIED DIFFERENTLY IN THE PERMIT. PLEASE REFER TO THE MONITORING AND REPORTING SECTION OF YOUR PERMIT FOR THE DATE YOUR FIRST DMR'S ARE DUE.

THE FOLLOWING TABLE MAY HELP EXPLAIN WHEN DMR'S ARE NORMALLY DUE:

JAN FEB MAR	- DUE ON -	APR 28, 197_
APR MAY JUN	- DUE ON -	JUL 28, 197_
JUL AUG SEP	- DUE ON -	OCT 28, 197_
OCT NOV DEC	- DUE ON -	JAN 28, 197_

ENCLOSED IS A SUPPLY OF DMR'S FOR YOUR USE IN COMPLYING WITH THE REQUIREMENTS OF THE SUBJECT NPDES PERMIT. THE ENCLOSED FORMS SHOULD BE SUFFICIENT FOR ONE YEAR'S REPORTING FOR THE ABOVE PERMIT. ANOTHER SUPPLY WILL BE SENT TO YOU IN APPROXIMATELY 23 MONTHS.

PLEASE REFER TO YOUR PERMIT NUMBER ON ANY CORRESPONDENCE CONCERNING YOUR PERMIT. SHOULD YOU NEED ADDITIONAL FORMS OR REQUIRE ASSISTANCE ON ANY MATTER CONCERNING YOUR NPDES PERMIT, PLEASE CONTACT THIS OFFICE AT THE LETTERHEAD ADDRESS OR AT AREA CODE 214-749-1983.

ENFORCEMENT DIVISION (6AEP)

ENCLOSURES